Which Imperium firmware is correct for my Imperium?

August, 2022

Imperium_fw_4.1_MIDI_only.syx

Standard configuration

This firmware is for all Imperium models that does not have the USB option card and/or the WiFi option card. This means that it can only communicate via MIDI. Check out our support video on how to update Imperium firmware via MIDI on 2400audio.com/support.

Imperium_fw_4.1_with_WiFi_or_USB.syx

With USB option and/or WiFi option

This firmware is for all Imperium models that has the USB option card and/or the WiFi option card. Check out our support video on how to update Imperium firmware via USB or WiFi on 2400audio.com/support.

My Imperium has a USB connector, do I have the USB option installed?

All Imperium models has the USB-B connector on the back. However, that does not mean that the USB option card is installed. The USB option enables Imperium control via USB. If the Mac/PC does not recognize the Imperium when plugged in via USB, the USB option card is not installed in the Imperium.

TouchOSC layout version 4

If you use TouchOSC to control the Imperium, you need to use TouchOSC Imperium layout version 4.0 if you update the Imperium firmware to version 4 or newer. This can also be found in the 2400 Audio download package. There are two variants of the layout, one for 1U models, and one for 2U models:

- 1U: Imperium_layout_all_1u_models_ver_4.0
- 2U: Imperium_layout_all_2u_models_ver_4.0